

806 W. LaLande Ave. Sublette, KS (620) 675-2222

Irrigation Well Test Results

Date: 08/09/25

Location: NW36 27-42

Flow: 308 GPM Speed: 1462 RPM

Water quality: Clear, no air, no sand

Pumping water level: N.A.-Water level tube is plugged

*Pressure: No pressure gauge at the well

Location: C36 27-42

Flow: 525 GPM Speed: 1380 RPM

Water quality: Clear, no air, no sand

Pumping water level: 350'

*Pressure: 3 PSI

^{*}There is a booster pump at the pivot. There is 25 PSI after the booster pump.