


TILE RECORD MAP



NAME Farmer's Nat'l Co Ken Wiesen

Section _____ Township _____ County _____

Contractor Jim Blood Date installed Spring 96

Amount of tile installed 5" _____ 6" _____ 8" _____

10" _____ 12" _____ Larger _____

Dean Bertelson (Tenant)

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.

IOWA DRAINAGE, INC.

SHEFFIELD, IOWA 50475

Jim Blood — Telephone 515-892-4330

